

Name/Location	Address	Ward	Designation	Listing description if applicable	Date of Listing	Planning policy constraints	Description	At Risk Register?	Ownership	Notes
Ornate arch off Wrights Lane	ARCH LOCATED TO THE SIDE OF 151-161 KENSINGTON HIGH STREET ACCESSED FROM WRIGHTS LANE	Abingdon	n/a	n/a	n/a	Edward's Square / Scarsdale & Abingdon, Article 4, No 100 -104	Arch comprising of sandstone sections interspersed with red brick. There is elaborate work on both pillars, with an ornate carved upper section. The top of the arch has included an inscribed date (1894), and a woman's face.	No	Owned	
Entrance arch to Park House between Numbers 7 and 11	ENTRANCE ARCH TO PARK HOUSE BETWEEN NUMBERS 7 AND 11, ONSLOW SQUARE SW7	Brompton and Hans Town	II	Circa 1846. Stucco. Segmental arch springing from simple piers, cornice over. Joins the terraces of Nos 1-7 (odd) and Nos 11-25 (odd) Onslow Square.	6/8/1973	Thurloe/ Smith's charity conservation area, critical drainage area, No 100 and 104 article 4	Plain arch rendered in white with a wrought iron electric gate, some notices including a CCTV warning sign. A retractable car boom is situated internally to the arch. Wooden panel lining interior of arch, with some splintering and scratches.	No	Owned	Significant presence of security features, flanked by Grade II listed buildings (9-25, 1-7 Onslow Square)
Ennismore Gardens Mews Arch	MEWS ARCH ADJOINING NUMBER 37, ENNISMORE GARDENS SW7	Brompton and Hans Town	II	Mews arch adjoining No 37 14.1.70 [formerly listed as Entrance Gateway to the Mews (adjoining No 37)]Mews arch. Mid C19. Stone. Roman Ionic colonnade with paired columns supporting entablature. Southern half in Royal Borough of Kensington and Chelsea. The asset was previously listed twice as List entry 1358148. This entry was removed from the List on 18/10/17	14/1/1970	Brompton	Tall Ionic arch with twin columns to either side of the highway. Arch partly support by the structure of No 37 Ennismore Gardens. Some discolouration with vegetative growth.	No	Unowned	
Shafto Mews	ENTRANCE ARCH FROM CADOGAN SQUARE, WITH FLANKING PAVILIONS, SHAFTO MEWS SW1, CHELSEA	Brompton and Hans Town	II	Archway. Circa 1880. Semi-circular arch of rusticated red brick with stone dressings and copings. Pilasters and entablature with Dutch gable above. Channelled brick walls on either side of the archway.	6/8/1973	Cadogan Square	Stereobate on front right hand side different to that on left hand side (one brick, other rendered which is discoloured). Front of arch in generally good condition	No	Unowned	
Shafto Mews rear boundary	REAR WALL FORMER REAR BOUNDARY OF SHAFTO MEWS AND BACKING ONTO CADOGAN SQUARE	Brompton and Hans Town	n/a	n/a	n/a	Hans Town	Ornate rear wall comprising of red brick	n/a	Owned	
Egerton Garden Mews	ENTRANCE FROM EGERTON TERRACE	Brompton and Hans Town	n/a	n/a	n/a	Thurloe/Smith's Charity	Two central columns crown main high way. Does not constitute a full arch. Two minor arches above each pedestrian footpath. Lower section of one half of pair coming away from wall. Arch derives support from wall and not the damaged pier. The remaining pier does not theoretically need the support base.	n/a	Unowned	
Onslow Mews West	Courtfield Mews West - ENTRANCE ARCH FROM CRANLEY PLACE, ONSLOW MEWS WEST SW7.	Courtfield	II	Circa 1865. Plain segmental headed stucco arch with dentil cornice over.	6/8/1973	Thurloe/ Smith's charity conservation area, no 100 and 104 article 4	Rendered white, dentils. Signage- road sign and parking warning. Some dark marks, especially from weathering at the bottom. Some areas where paint has peeled.	No	Unowned	Attached to grade II listed building on right hand side (11-19 Cranley Place)
Onslow Mews East	ENTRANCE ARCH FROM CRANLEY PLACE, ONSLOW MEWS EAST SW7	Courtfield	II	Circa 1855. Plain segmental headed stucco arch with dentil cornice over.	6/8/1973	Thurloe/ Smith's charity conservation area, no 100 and 104 article 4	Rendered white & dentil cornice. Width signage, road signage, warning, all in good condition. Car boom situated internally to the mews.	No	Owned	Attached to grade II listed building on left hand side (1-10 Cranley Place)
Ensor Mews	ENTRANCE ARCH AND SCREEN WALL ON CRANLEY GARDENS, ENSOR MEWS SW7	Courtfield	II	ENSOR MEWS SW7 TQ 2678 SE 55/4 6.8.73 Entrance Arch and Screen Wall on Cranley Gardens II Circa 1870. White brick semi-circular arch flanked by 3 blank bays on the north, divided by pilasters and with recessed blank arches. Above is a parapet with a balustrade. Between Nos 79-91 (odd) Onslow Gardens and Nos 1-11 (odd) Cranley Gardens.	6/8/1973	Thurloe/Smith's Charity	Weathered patination. Ensor Mews signage affixed to southern column	No	Unowned	SW7 3BT - (off Cranley Gardens) directly connected to 17 Onslow Gardens (Welcome Trust)
Colbeck Mews	ENTRANCE ARCH FROM COLLINGHAM ROAD, COLBECK MEWS SW7	Courtfield	II	Circa 1875. Stucco carriage arch and side arches In the form of triumphal arch. Round headed central arch with moulded architrave and vermiculated keystone and panels in the spandrels. Cornice and parapet above. The side arches have-square heads with raised panels above.	6/8/1973	Courtfield Gardens conservation area no 100 and 104 Article 4, critical drainage area Kensington	Appearance in good condition. Some vehicle damage the right handside pillar a few years ago.	No	Unowned	SW5 0LS - integral to 10 Colbeck Mews. Works to construct basement have structurally supported mews
Ensor Mews	ENTRANCE ARCH AND SCREEN WALL ON ONSLOW GARDENS, ENSOR MEWS SW7, CHELSEA	Courtfield	II	Circa.1870. White brick semi-circular, arch flanked by .-3 bays on the north and 6 on the south each with a blank recessed arch supported on pilasters. Above the whole facade runs a balustraded parapet. Adjoins Nos 79-91 (odd) Onslow Gardens	3/8/1973	Thurloe/Smith's Charity	Good condition	No	Owned	Southern section - RBKC. Northern section - 94 Onslow Gardens

Name/Location	Address	Ward	Designation	Listing description if applicable	Date of Listing	Planning policy constraints	Description	At Risk Register?	Ownership	Notes
Gaspar Mews	ENTRANCE ARCH FROM COURTFIELD GARDENS, GASPAR MEWS SW5, CHELSEA	Courtfield	II	Circa 1870. Stucco carriage arch with foot arches on either side. Plain piers channelled arch, vermiculated keystone, pediment.	6/8/1973	Courtfield	Very poor condition.	Yes	Unowned	
Manson Mews	ENTRANCE ARCH FROM QUEEN'S GATE, MANSON MEWS, CHELSEA	Courtfield	II	Archway. Circa 1860. Channelled stucco. Carriage arch and two foot arches. Raised central portion supported by scrolled ramps. Vermiculated keystone and cornice.	6/8/1973	Queen's Gate conservation area, Courtfield neighbourhood area, critical drainage area, no 100 and 104 article 4	Black paint at the feet of columns, remaining structure painted in light colour. Signage for mews and rubbish warning affixed to columns. Signs of weathering/ damp marks, and weeds growing on top of arch.	No	Unowned	Grade II listed buildings either side- 88-99 Queen's Gate and 100-107 Queen's Gate
Stanhope Mews East	ENTRANCE ARCH FROM CROMWELL ROAD, STANHOPE MEWS EAST SW7, KENSINGTON	Courtfield	II	Circa 1868. Stucco carriage arch with small flanking arches, channelled stucco piers, simple moulded architrave and keystone, cornice over.	6/8/1973	Queens Gate conservation area no 100 and 104 Article 4 , critical drainage area Kensington	A handsome Classical type arch, with simple but elegant detailing. Some very light discolouration but otherwise in good condition. Historic signifiace of the arch is somewhat diminished by the adjacent BT phone box.	No	Unowned	Adjacent to Derwent House & 57B Cromwell Road
Stanhope Mews West	ENTRANCE ARCH FROM STANHOPE GARDENS, STANHOPE MEWS WEST SW7, KENSINGTON	Courtfield	II	Circa 1868. Carriage arch with small flanking arches. Channelled stucco piers and spandrels with rusticated architrave cornice and parapet over. Balustrade over side arches.	6/8/1973	Queens Gate conservation area, no 100 and 104 Article 4	The front facade on the left handside has patches of plaster and paintwork missing. Paint has also come off the bottom of the left pillar. No visible cracks. Dirty at the bottom of all pillars.	No	Unowned	
Sumner Place Mews	ENTRANCE ARCH FROM SUMNER PLACE, SUMNER PLACE MEWS SW7, CHELSEA	Courtfield	II	Circa 1850. Segmental stucco arch with channelled piers and moulded architrave dentil cornice over. Adjoins Nos 13-23 (odd) Sumner Place.	6/8/1973	Thurloe/ Smith's charity conservation area, no 100 and 104 article 4	The columns of the arch are partly enclosed by black railings. CCTV camera and warning signs affixed to the columns of the arch. Dentils run along the top sectio of the arch below a coping stone. The façade is partingin white and in good condition.	No	Unowned	Attached to grade II listed building on left hand side (13-23 Sumner Place)
Stanhope Mews West	ENTRANCE ARCH FROM CROMWELL ROAD, STANHOPE MEWS WEST SW7, KENSINGTON	Courtfield	II	Circa 1868. Single carriage arch. Channelled stucco piers, simple moulded architrave and keystone, cornice over.	6/8/1973	Queens Gate conservation area, no 100 and 104 Article 4	Slight crack to the right handside of upper arch. Dirty rain marks along the top and bottom.	No	Unowned	
Gaspar Close	ENTRANCE ARCH FROM COURTFIELD GARDENS, GASPAR CLOSE SW5, CHELSEA	Courtfield	II	Archway: Circa 1870. Stucco. Plain piers, channelled arch, vermiculated keystone pediment.	6/8/1973	Courtfield	General weatherng but nothing substantial. White rendered facades. The asset comprises of an important Classical arch.	No	Owned	Stucco carriage arch, c1870, with foot arches on either side. The central arch has plain piers, a central channelled arch with vermiculated keystone, and pediment. The stucco has
Legacy arch Courtfield Mews	ENTRANCE ARCH FROM COURTFIELD ROAD INTO COURTFIELD MEWS	Courtfield	n/a	n/a	n/a	Courtfield	Lower footings retained from an arch which stood at the entrance into the mews at some point in time - a likely remant of bomb damage. The footings of the former arch are discoloured and have moss/light vegetation growing from the top most surface,	n/a	Owned	
Dove Mews	COLUMNED ENTRANCE FROM BINA GARDENS	Courtfield	n/a	n/a	n/a	None	Tall white square columns with a horizontal band and top stone. Rendered in white with very light discolouration. Comprise two columns to either side of the highway which flank the entrance into the mews. Although non listed the columns have amenity value which is worth safeguarding.	n/a	Unowned	
Holly Mews	COLUMNED ENTRANCE INTO HOLLY MEWS	Courtfield	n/a	n/a	n/a		White columns with decorative capping stones.	n/a	Unowned	
Sydney Mews off Fulham Road	LOCATION BETWEEN 50 AND 48 FULHAM ROAD	Courtfield	n/a	n/a	n/a	Thurloe/Smith's Charity	White arch incorporated into the built form of shop frontages and residential premises	n/a	Owned	
Sydney Close	LOCATED BETWEEN 74 AND 76 FULHAM ROAD	Courtfield	n/a	n/a	n/a	Thurloe/Smith's Charity	White arch incorporated into the built form of shop frontages and residential premises	n/a	Owned	
Astwood Mews	ENTRANCE COLUMNS ACCESSED FROM COURTFIELD ROAD	Courtfield	n/a	n/a	n/a	Courtfield	Unrendered brick columns set behind sweeping black railings.	n/a	Unowned	

Name/Location	Address	Ward	Designation	Listing description if applicable	Date of Listing	Planning policy constraints	Description	At Risk Register?	Ownership	Notes
Kensal Green Cemetery Arch	ENTRANCE GATEWAY OPPOSITE WELLINGTON ROAD, HARROW ROAD W10, KENSAL GREEN CEMETERY, KENSINGTON	Delgamo	II*	Also Known As: Entrance Arch, HARROW ROAD W10, KENSAL GREEN CEMETERY Entrance Archway. 1832-34 by John Griffith for the General Cemetery Company. Portland stone, with rendered brick additions. Central arched opening, coffered within, flanked by fluted Doric columns, with attic above; side sections with blind windows (open to rear), pylon-shaped to ground floor, square to first floor, with pilasters at ends; continuous Doric frieze. Chimneys lowered in recent years. Cast iron gates with spearhead finials. Single-storey extensions to each side containing offices (on west side, considerably extended in C20) and former superintendent's quarters (on east). Interior of arch contains living quarters.	15/4/1969	Kensal Green cemetery conservation area, site of nature conservation importance (Kensal Green cemetery), archaeological priority area (Kensington and Chelsea cemeteries), no 100 and 104 article 4	Very large arch, goes back a few metres with columns and buildings either side. Vegetation climbing up arch, with a large amount on left hand side of exterior and right hand side of interior. Exposed cement, generally good condition but some signs of weathering and age, particularly at feet of columns. Also some small structural damage with cement missing on left hand side. Painted in walkway internal to arch, which is in poor condition with cracks, peeling, and mould. Notice board and door inside archway. Small areas on column inside cemetery have been painted on (presumably to test for repainting)	No	Owned	Grade II listed perimeter wall on left hand side. Buildings with windows form either side of arch, notice board owned by Friends of Kensal Green cemetery affixed internally to arch
Laverton Mews	ENTRANCE ARCH FROM LAVERTON PLACE, LAVERTON MEWS, CHELSEA	Earl's Court	II	Archway. Circa 1866. Carriage arch with side arches. White brick with semi-circular heads, stucco architraves and vermiculated keystones. Bracketted cornice over.	6/8/1973	Courtfield conservation area, no 100 and 104 Article 4	No paintwork, brickwork is exposed. Some vegetation growing on the right handside (front and back; appears to be vines).	No	Unowned	
Holland Park Mews	ENTRANCE FROM HOLLAND PARK (WEST) INTO HOLLAND PARK MEWS	Holland	II	Archway. 1862 onwards. Roman cement. Giant archway of triumphal character in thin screen form. Rusticated walling. Segmental headed carriage arch; lower smaller pedestrian arches with round heads. Entablature over. Panelled attic with pilasters, cornice and blocking course.	15/4/1969	Holland Park conservation area, critical drainage area, no 100 and 104 article 4	Exposed cement, not painted over. Some discolouration, particularly green marks from weathering at the feet of the columns and lots of small white marks and other significant weathering marks along top cornice. Some damage to curve of arch, presumably from lorries but not significant. 'Holland Park Mews' carved into had of arch at exterior, in good condition. Damage to feature below sign	No	Unowned	
Linden Mews	ENTRANCE ARCH FROM LINDEN GARDENS, LINDEN MEWS W2, KENSINGTON	Pembridge	II	Archway. Circa 1875. Stucco arch with moulded architrave and vermiculated keystone. Plain piers and pilasters. Pediment enclosing foliage and an escutcheon, urn finials.	6/8/1973	Pembridge conservation area, no 100 and 104 article 4	Painted white, with paint slightly off-colour, and some cracks and peeling, could do with sanding and repainting. Walls attached to either side of arch, with metal fence across arch and door system attached to inside. Weeds growing at top left hand side of arch and around the bottom. Urns at top on either side of arch, right one has dark marks on it. Other decorative features in good condition, with no structural damage. Large crack mid-way up left hand side of arch. Some other small marks of damage.	No	Linden Mews Limited	Closed gate across arch blocking entrance to mews, significant security signage
Cornwall Mews South	WEST ENTRANCE ARCH FROM GRENVILLE PLACE, CORNWALL MEWS SOUTH SW7, KENSINGTON	Queens Gate	II	Circa 1865. Rusticated semi-circular stucco arch with cornice over.	6/8/1973	Cornwall conservation area no 100 and 104 Article 4, critical drainage area Kensington	Plane undecorated arch with cornice. Light weathering to the main elevations and darker discolouration below the cornice. Cornwall Mews South sign affixed to column.	No	Unowned	NGL510771
Grenville Mews	ENTRANCE ARCH FROM HARRINGTON GARDENS, WITH FLANKING PAVILIONS, GRENVILLE MEWS, KENSINGTON	Queens Gate	II	Circa 1870. Stucco. Rusticated carriage arch with square-headed foot arches on either side. Pilasters, entablature and pediment to the main arch. The side pavilions have 5 bays of blank round-headed arches with a crowning balustrade.	6/8/1973	Queens Gate	Subsumed in the built form of the building. Arch retained as a form of detailing within the rear façade of Gloucester Hotel, Harrington Gardens	No	Owned	
Cornwall Mews South	EAST ENTRANCE ARCH FROM GRENVILLE PLACE, CORNWALL MEWS SOUTH SW7	Queens Gate	II	Circa 1865. Rusticated semi-circular stucco arch with cornice over.		Cornwall conservation area, no 100 and 104 Article 4. Kensington Critical Drainage Area	Weathered patination. Climbing vegetation affixed to front façade at some stage. Budlia growing from top of capping stone. Discolouration below top. Sign affixed to southern column.	No	Unowned	
Elvaston Mews	ENTRANCE ARCH FROM ELVASTON PLACE, ELVASTON MEWS SW7, KENSINGTON	Queens Gate	II	Archway. Circa 1865. Two stone Ionic columns support entablature and broken segmental pediment with floral swags and escutcheon.	6/8/1973	Queens Gate conservation area, no 100 and 104 Article 4. Kensington Critical Drainage Area	Strong discolouring at the top of the arch. Discolouring present along both pillars. Faint cracks present on both pillars.	No	Unowned	
Kynance Mews	EAST ENTRANCE ARCH FROM LAUNCESTON PLACE, KYNANCE MEWS SW7, KENSINGTON	Queens Gate	II	Archway. Circa 1860. Simple stucco arch with rusticated piers and vermiculated architrave, cornice over.	6/8/1973	No. 100 -104 Article 4. De Verre Conservation area. Kensington Critical Drainage Area	High quantities of vines hanging from top of arch appearing to have been spread from the neighboring building obstructing the signage to the mews which is affixed to the pillar. Evidence of weathering.	No	Unowned	
Kynance Mews	WEST ENTRANCE ARCH FROM LAUNCESTON PLACE, KYNANCE MEWS SW7, KENSINGTON	Queens Gate	II	Archway. Circa 1860. Simple stucco arch with rusticated piers and vermiculated architrave, cornice over.	6/8/1973	No. 100 -104 Article 4. De Verre Conservation area. Kensington Critical Drainage Area	Wooden panels surround base of pillars. Evidence of weathering and cracks are present at the back of the arch	No	Unowned	
Queen's Gate Place Mews	ENTRANCE ARCH FROM QUEEN'S GATE PLACE, QUEEN'S GATE PLACE MEWS SW7, KENSINGTON	Queens Gate	II	Mid C19. Elaborate triple archway; stuccoed Ionic order, segmental pediment (connecting Nos 18 and 19 Queen's Gate Place SW7).	6/8/1973	No. 100 -104 Article 4. De Verre Conservation area. Kensington Critical Drainage Area	Good condition, signs of weathering/marks on the top of the western pillar	No	Unowned	

Name/Location	Address	Ward	Designation	Listing description if applicable	Date of Listing	Planning policy constraints	Description	At Risk Register?	Ownership	Notes
Kynance Mews	ENTRANCE ARCH FROM GLOUCESTER ROAD, KYNANCE MEWS SW7, KENSINGTON	Queens Gate	II	Archway. Circa 1860. Simple stucco arch 'with rusticated piers and vermiculated architrave, cornice over.	6/8/1973	No. 100 -104 Article 4. Queensgate Conservation area. Kensington Critical Drainage Area	Marks visible at the top of the arch on the side facing Gloucester Road, otherwise in good condition.	No	Unowned	
Albert Mews	ENTRANCE ARCH FROM VICTORIA GROVE, ALBERT MEWS W8, KENSINGTON	Queens Gate	II	Circa 1845. Round-headed stucco arch with rusticated architrave and a keystone with a male head; cornice over. Adjoins Nos 19-26 (consec.), Victoria Grove.	6/8/1973	No. 100 -104 Article 4. De Verre Conservation area. Kensington Critical Drainage Area	Paint is in good condition as is the overall state of the arch. No evidence of cracking, weathering or instability	No	Owned	
Osten Mews	ENTRANCE ARCH FROM EMPEROR'S GATE, OSTEN MEWS, KENSINGTON	Queens Gate	n/a	n/a	n/a	Cornwall conservation area, Article 4, No 100-104	Arch is built out of red brick, and seems to be in relatively good condition. There is evidence that some of the brick work has been replaced, and black marks in certain locations.	No	Unowned	Unable to find on Historic England, however the website 'Everchanging Mews' posted this: Osten Mews is a cobbled cul-de-sac and through road off Emperor's Gate in the
Redcliffe Mews	ENTRANCE ARCH FROM HARCOURT TERRACE, REDCLIFFE MEWS SW10, CHELSEA	Redcliffe	II	1869. Stucco. Round headed arch flanked by paired Roman Doric half columns; broken pediment over. The name and date is engraved in the pediment.	6/8/1973	The Boltons Conservation Area, Numbers 100 & 104 Article IV	Front of arch in reasonable condition. Rendered white, dentil cornice. CCTV sign on front right hand side.	No	Owned	